

LUFTHANSA TECHNIK INTERCOAT GMBH

MAINTENANCE CAPABILITY LIST FOR CAAC

Certificate No.: **F04900358**

Issue date: November 27th, 2003

Revision No.: **11**

Revision Date: **October 23rd, 2025**

Address: Kisdorfer Weg 36-38
D-24568 Kaltenkirchen
Germany

Statement of Compliance

All the items listed in the maintenance capability list should not exceed the approved item scope in the CAAC Certificate No. F04900358. Lufthansa Technik Intercoat GmbH ensures that the facilities, tool and equipment, airworthiness data, and personnel should be provided for carrying out the maintenance work listed in the maintenance capability list, the developed working procedures conform with the requirements of CCAR-145 at any time.

Any change or update of the maintenance capability list should be submitted to CAAC for acceptance.

Name: Ms. Melina Remers

Signature: 

Position: Quality Assurance Manager

Date: October 23rd, 2025

Lufthansa Technik Intercoat GmbH

Company Maintenance Capability List for CAAC

LIST OF EFFECTIVE PAGES

CAAC Certificate No. : F04900358

Revision No. : 11

Pages	Revision Date	Item Quantity	Remark
Front page of Maintenance Capability List	October 23 rd , 2025	n/a	None
Statement of Compliance of MCL	October 23 rd , 2025	n/a	None
The List of Effective Pages of MCL	October 23 rd , 2025	n/a	None
Page 01- 12 (items list)	October 23 rd , 2025	176	Part numbers added for two existing repairs, changes marked with A

Approved by: Ms. Melina Remers
Position: Quality Assurance Manager

Signature:

Date: October 23rd, 2025

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

No.	Part Number	Description	ATA Chapter	Manufacturer	Maintenance functions	Technical Data	Major Equipment	Remark
1.	5006907, 5006907A, 5006907B	Gear Pump Hsg	73-11	Hamilton Sundstrand	Repair	LTI Repair Scheme #205-0070	N/A	Minor Repair Approval by EASA DO21J
2.	1211318-203, 1211318-225	Actuator Gland	75-32	Arkwin	Repair	LTI Repair Scheme #205-0660	N/A	Minor Repair Approval by EASA DO21J
3.	6437A11G700	Rotor & Magnet Assy	73-31	Ametek	Repair	LTI Repair Scheme #205-0901	N/A	Minor Repair Approval by EASA DO21J
4.	350-713-502-0, 351-703-101-0	Body Assy - VSV Actuator	75-32	General Electric	Repair	LTI Repair Scheme #205-0910	N/A	Minor Repair Approval by EASA DO21J
5.	838011-1, 838012-1	Gear Housing Assy	73-11	Argo-Tech	Repair	LTI Repair Scheme #205-0920	N/A	Minor Repair Approval by EASA DO21J
6.	40P6240	Housing Assy, Pump	79-21	General Electric	Repair	LTI Repair Scheme #205-1000	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
7.	301-811-001-0, 301-811-201-0, 301-811-401-0, 301-811-601-0, 301-812-001-0, 336-010-301-0, 336-010-501-0, 336-010-601-0, 336-010-801-0, 41P1007, 41P1013, 41P1035, 41P1036, 301-811-801-0, 336-010-901-0, 336-045-001-0, 335-294-500-0, 335-294-501-0, 335-294-600-0, 335-294-601-0, 335-294-800-0, 335-294-801-0, 335-295-200-0, 335-295-201-0, 335-299-101-0, 335-299-102-0, 337-075-601-0, 337-075-801-0, 337-076-001-0, 337-076-201-0, 337-076-401-0, 337-076-602-0, 337-084-001-0, 337-084-201-0, 337-084-401-0, 337-084-601-0, 337-084-801-0, 337-085-001-0	Spacer Assembly	79-21	CFMI	Repair	LTI Repair Scheme #205-1010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

8.	350-051-101-0, 350-052-101-0, 350-053-101-0, 350-054-301-0, 350-054-801-0, 350-055-301-0, 350-055-901-0, 350-056-501-0, 350-057-001-0, 350-057-302-0, 350-057-402-0	Spacer Assembly	79-21	SNECMA	Repair	LTI Repair Scheme #205-1010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
9.	40P6299, 40P6320, 40P6324, 40P6328, 40P6334, 40P6344, 40P6345, 40P6347, 40P6348, 40P6351, 40P6371, 40P6384, 40P6387, 40P6389, B1316-00537, B1316-05424	Spacer Assembly	79-21	Techspace Aero	Repair	LTI Repair Scheme #205-1010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
10.	5863410-101, 5923004-101	Actuator Body	75-21	Parker Hannifin	Repair	LTI Repair Scheme #205-2060	N/A	Minor Repair Approval by EASA DO21J
11.	788290-1, 788290-2, 813575-1, 819812-1, 819812-2	Actuator Housing	75-31	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-1500	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
12.	790170-1, 790170-2, 814882-1, 814882-2	Hsg Assembly	75-31	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-1510	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
13.	5009015	Pump Housing	79-21	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-1710	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
14.	792397-3	Diverter Piston & Housing Set	73-21	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-1800	N/A	Minor Repair Approval by EASA DO21J
15.	3901324-101	Cylinder Assy	75-31	Parker Hannifin	Repair	LTI Repair Scheme #210-2010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
16.	3891234-101, 3891234-102	Actuator Body	75-32	Parker Hannifin	Repair	LTI Repair Scheme #210-2020	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
17.	5007424	Lube & Scavenge Pump Hsg.	79-21	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-2100	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
18.	5007475, 5007475-1	Pump Cover	79-21	Hamilton Sundstrand	Repair	LTI Repair Scheme #210-2101	N/A	Minor Repair Approval by EASA DO21J
19.	1192-113-1	End Cap	32-32	Dowty	Repair	LTI Repair Scheme #215-0010	N/A	Minor Repair Approval by EASA DO21J
20.	65B1564-1, 65B1564-2, 65B1564-5, 65B1564-6, 65B1564-7, 65B1564-8, 65B1564-9, 65B1564-10	Head End	32-11	Boeing	Repair	LTI Repair Scheme #215-0150	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

21.	51634, 51635	Manifold Assy	32-31	Eaton-Vickers	Repair	LTI Repair Scheme #215-0160	N/A	Minor Repair Approval by EASA DO21J
22.	P665A0111-00	Manifold Assy	27-60	Moog	Repair	LTI Repair Scheme #215-0170	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
23.	2671727	Manifold	32-30	Parker Hannifin	Repair	LTI Repair Scheme #215-0410	N/A	Minor Repair Approval by EASA DO21J
24.	2671770, 2671771	Swivel Assy RH & LH	32-30	Parker Hannifin	Repair	LTI Repair Scheme #215-0411	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
25.	65B01514-9, 65B01514-10, 65B01514-11, 65B01514-12	Trunnion	32-51	Boeing	Repair	LTI Repair Scheme #215-0430	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
26.	1204-22	Cylinder Assy	32-34	Woodward	Repair	LTI Repair Scheme #215-0470	N/A	Minor Repair Approval by EASA DO21J
27.	65-44711-1, 65-44711-5	Barrel Assembly	32-50	Boeing	Repair	LTI Repair Scheme #215-1000	N/A	Minor Repair Approval by EASA DO21J
28.	383965-3	Manifold Assy	32-50	Parker Hannifin	Repair	LTI Repair Scheme #215-1080	N/A	Minor Repair Approval by EASA DO21J
29.	65-44785-1	Manifold Assy	27-81	Boeing	Repair	LTI Repair Scheme #215-1210	N/A	Minor Repair Approval by EASA DO21J
30.	39-35310	Manifold	32-40	Crane	Repair	LTI Repair Scheme #215-1550	N/A	Minor Repair Approval by EASA DO21J
31.	762068-02 thru -09	Input Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-1700	N/A	Minor Repair Approval by EASA DO21J
32.	1702760, 762074-02, 762074-03	End Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-1710	N/A	Minor Repair Approval by EASA DO21J
33.	790400-2, 797616-2	Act Housing - Press. Reg. & Shutoff Valve	36-11	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-2000	N/A	Minor Repair Approval by EASA DO21J
34.	790400-2	Act Housing - Press. Reg. & Shutoff Valve	36-12	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-2000	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
35.	531002-3	Housing Assy	21-20	Honeywell	Repair	LTI Repair Scheme #215-2003	N/A	Minor Repair Approval by EASA DO21J
36.	1171-46, 1171-46-1	Cylinder Assy	32-50	Dowty	Repair	LTI Repair Scheme #215-2130	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
37.	3169904-1, 3169904 -9	Valve Body	21-61	Honeywell	Repair	LTI Repair Scheme #215-2260	N/A	Minor Repair Approval by EASA DO21J
38.	3169904-2	Valve Body	21-51	Honeywell	Repair	LTI Repair Scheme #215-2260	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

39.	3169904-3	Valve Body	21-60	Honeywell	Repair	LTI Repair Scheme #215-2260	N/A	Minor Repair Approval by EASA DO21J
40.	3169904-5	Valve Body	21-50	Honeywell	Repair	LTI Repair Scheme #215-2260	N/A	Minor Repair Approval by EASA DO21J
41.	887511-4	Valve Body	21-51	Honeywell	Repair	LTI Repair Scheme #215-2280	N/A	Minor Repair Approval by EASA DO21J
42.	733554A thru E, 736691A thru F, 754278A, 754278B, 759462-01, 759462-02	Input Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-2720	N/A	Minor Repair Approval by EASA DO21J
43.	3170236-1	Body, Sleeve & Spool Assy	27-11	MOOG	Repair	LTI Repair Scheme #215-2740	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
44.	3170284-1, -2, 3170285-SERIES, 3314810, 3315102	Body, Sleeve & Spool Assy	27-11	MOOG	Repair	LTI Repair Scheme #215-2750	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
45.	3175592	Barrel, Aft	27-11	MOOG	Repair	LTI Repair Scheme #215-2760	N/A	Minor Repair Approval by EASA DO21J
46.	275N1228-1, 275N1228-3	Trunnion	32-51	Boeing	Repair	LTI Repair Scheme #215-4030	N/A	Minor Repair Approval by EASA DO21J
47.	615050-101, 615050-102	Manifold Assy	32-50	Parker Hannifin	Repair	LTI Repair Scheme #215-7002	N/A	Minor Repair Approval by EASA DO21J
48.	3911440-105	Manifold	32-35	Parker Hannifin	Repair	LTI Repair Scheme #215-7003	N/A	Minor Repair Approval by EASA DO21J
49.	808638-1	Housing, Valve & Actuator	21-52	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7150	N/A	Minor Repair Approval by EASA DO21J
50.	810618-2, 810618-5	Housing, Valve & Actuator	21-35	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7160	N/A	Minor Repair Approval by EASA DO21J
51.	3931240-104	Manifold	27-52	Parker Hannifin	Repair	LTI Repair Scheme #215-7500	N/A	Minor Repair Approval by EASA DO21J
52.	3931240-103	Manifold	27-80	Parker Hannifin	Repair	LTI Repair Scheme #215-7500	N/A	Minor Repair Approval by EASA DO21J
53.	769097-01, 769097-02	Input Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7700	N/A	Minor Repair Approval by EASA DO21J
54.	757145, 757145B	Cover Assembly	24-25	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7770	N/A	Minor Repair Approval by EASA DO21J
55.	758491A	Housing and Gear Set	24-25	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7771	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
56.	757069A, 757069C	Housing	24-25	Hamilton Sundstrand	Repair	LTI Repair Scheme #215-7774	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

57.	4034-580	HMU Housing	73-21	Woodward	Repair	LTI Repair Scheme #225-0020	N/A	Minor Repair Approval by EASA DO21J
58.	GA71187	Body Assy	78-31	Goodrich Aerospace	Repair	LTI Repair Scheme #225-0060	N/A	Minor Repair Approval by EASA DO21J
59.	1211313-105-1, 1211313-105-2, 1211313-105-3	Actuator Body	75-32	Arkwin	Repair	LTI Repair Scheme #225-0770	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA (directly)
60.	1211313-215, 1211313-218	Rod End Clevis	75-32	Arkwin	Repair	LTI Repair Scheme #225-0790	N/A	Minor Repair Approval by EASA DO21J
61.	324551, 324551-1	Actuator Body	75-23	Whittaker	Repair	LTI Repair Scheme #225-2080	N/A	Minor Repair Approval by EASA DO21J
62.	217621-1, 217621-2	Pump Cover Assembly	73-11	Argo-Tech	Repair	LTI Repair Scheme #225-2181	N/A	Minor Repair Approval by EASA DO21J
63.	3231756-1, 3231756-3	Bearing Housing	75-31	Honeywell	Repair	LTI Repair Scheme #225-2270	N/A	Minor Repair Approval by EASA DO21J
64.	3231782-1, 3231782-2	Gear Housing Assy	75-31	Honeywell	Repair	LTI Repair Scheme #225-2280	N/A	Minor Repair Approval by EASA DO21J
65.	219310-1, 219820-1	Gear Housing Assy	73-11	ArgoTech	Repair	LTI Repair Scheme #225-2520	N/A	Minor Repair Approval by EASA DO21J
66.	219316-1	Bearing Plate	73-11	ArgoTech	Repair	LTI Repair Scheme #225-2521	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
67.	A88542	Body Assy	75-22	Messier-Dowty	Repair	LTI Repair Scheme #225-2550	N/A	Minor Repair Approval by EASA DO21J
68.	GA72166	Body Assy	75-23	Messier-Dowty	Repair	LTI Repair Scheme #225-2550	N/A	Minor Repair Approval by EASA DO21J
69.	301-910-405-0	LPT ACC Valve - Lower & Upper Housing	75-22	Snecma	Repair	LTI Repair Scheme #225-2560-1	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
70.	1FA1401248, 1FA1401281	Cylinder	78-31	Triumph	Repair	LTI Repair Scheme #225-2590	N/A	Minor Repair Approval by EASA DO21J
71.	3504976-2, 3504976-3	Housing Assy	80-11	Honeywell	Repair	LTI Repair Scheme #225-2600	N/A	Minor Repair Approval by EASA DO21J
72.	336-010-210-0	Housing	79-21	CFMI	Repair	LTI Repair Scheme #225-2790	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
73.	160564-1, 160564-2	Oil Cooler	49-94	Honeywell	Repair	LTI Repair Scheme #240-0080	N/A	Minor Repair Approval by EASA DO21J
74.	3880942-1	Oil Pressure Gear Hsg. Set	49-91	Aero Controlex	Repair	LTI Repair Scheme #240-0220	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

75.	70720601-1, 70720601-2	LC Bearing Support Housing	49-24	Honeywell	Repair	LTI Repair Scheme #240-0230	N/A	Minor Repair Approval by EASA DO21J
76.	341081-100, 341081-101	Bell Crank	27-34	Goodrich Aerospace	Repair	LTI Repair Scheme #245-0050	N/A	Minor Repair Approval by EASA DO21J
77.	490152	Cover, Screw Jack Assembly	27-44	Goodrich Aerospace	Repair	LTI Repair Scheme #245-0070	N/A	Minor Repair Approval by EASA DO21J
78.	A88223, A88223-1 thru -7	Body Assy - Hydraulic Ctrl Unit	32-57	Messier-Dowty	Repair	LTI Repair Scheme #245-0110	N/A	Minor Repair Approval by EASA DO21J
79.	114095206, 114095209, 114095300	Housing Assembly	32-11	Messier-Dowty	Repair	LTI Repair Scheme #245-0120	N/A	Minor Repair Approval by EASA DO21J
80.	114354202, 114354610	Housing and Plug Subassembly	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-0120	N/A	Minor Repair Approval by EASA DO21J
81.	201419202, 201419620	Cap - Subassy	32-11	Messier-Dowty	Repair	LTI Repair Scheme #245-0130	N/A	Minor Repair Approval by EASA DO21J
82.	201404202, 201419200, 201419600	Housing - Subassy	32-11	Messier-Dowty	Repair	LTI Repair Scheme #245-0131	N/A	Minor Repair Approval by EASA DO21J
83.	201160603	Torque Link Pin	32-11	Messier-Dowty	Repair	LTI Repair Scheme #245-0141	N/A	Minor Repair Approval by EASA DO21J
84.	201383604	Torque Link Pin	32-12	Messier-Dowty	Repair	LTI Repair Scheme #245-0142	N/A	Minor Repair Approval by EASA DO21J
85.	114193200, 201590201, 201697205, 201697206, 114193240, 201590200, 201697201, 201697202, , 201697208, 201697211, 201697212, 201697214, 201697219	Cylinder & Cylinder Subassembly	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-0150	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
86.	114193300, 114193624	Valve Subassy	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-0151	N/A	Minor Repair Approval by EASA DO21J
87.	114193301, 114193302, 114193625	Valve Subassy	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-0152	N/A	Minor Repair Approval by EASA DO21J
88.	D59775, D65235, D65235-1	Cylinder	32-27	Messier-Dowty	Repair	LTI Repair Scheme #245-0160	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
89.	D59421, D59421-1, D65540, GA62754, GA63497, GA65936	Cylinder	32-37	Messier-Dowty	Repair	LTI Repair Scheme #245-0175	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
90.	D61622, D61624, GA63723, GA63736	Body	32-37	Messier-Dowty	Repair	LTI Repair Scheme #245-0176 / 245-0177	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

91.	A88393-4, A88393-5, C24737002, C24737002-2, C24737002-4, C72146, C72146-1, C72146-2, C72146-3	Normal Brake Manifold Assy	32-47	Messier-Dowty	Repair	LTI Repair Scheme #245-0180	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
92.	30-1026001-01, 50-1026001-01	Cylinder Assy / Cylinder	32-33	Messier-Bugatti-Dowty	Repair	LTI Repair Scheme #245-0190	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
93.	H10546200, H10546203	Cylinder Subassembly	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-0260	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
94.	A88414-5	Body (LH)	32-43	Messier-Dowty	Repair	LTI Repair Scheme #245-0280	N/A	Minor Repair Approval by EASA DO21J
95.	81205029, 81205883, 81205885, 81205913, 81207678, 81207691, 81207700	Generator Housing	24-23	Safran	Repair	LTI Repair Scheme #245-0290	N/A	Minor Repair Approval by EASA DO21J
96.	21033-01, 21043-01	GBX Hsg Feedback Side & Motor Side	21-31	Nord-Micro	Repair	LTI Repair Scheme #245-0310	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
97.	4021-20391	Housing Assy - Feedback Side	21-31	Nord-Micro	Repair	LTI Repair Scheme #245-0320	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
98.	27A01-30100-10, 27A04-30100-001	Body - Valve Housing	32-47	Messier-Dowty	Repair	LTI Repair Scheme #245-0330	N/A	Minor Repair Approval by EASA DO21J
99.	A89383, A89383-2, A89383-6, A89383-8	Body	32-53	Messier-Dowty	Repair	LTI Repair Scheme #245-1100	N/A	Minor Repair Approval by EASA DO21J
100.	A89404	Cylinder	32-53	Safran	Repair	LTI Repair Scheme #245-1110	N/A	Minor Repair Approval by EASA DO21J
101.	A88778-2, A88778-3	Manifold Assy	32-47	Safran	Repair	LTI Repair Scheme #245-1200	N/A	Minor Repair Approval by EASA DO21J
102.	3456-031, 3455-031B, 3455-031BR	Body	21-52	Liebherr Aerospace	Repair	LTI Repair Scheme #245-2230	N/A	Minor Repair Approval by EASA DO21J
103.	3169904-7, 3169904-8	Valve Body	21-53	Allied Signal	Repair	LTI Repair Scheme #245-2260	N/A	Minor Repair Approval by EASA DO21J
104.	201480200	Cylinder Subassy	32-12	Messier-Dowty	Repair	LTI Repair Scheme #245-2400	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
105.	15505-101, 15506-101	Cylinder Assy	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-2480	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
106.	114256310, 114256320, 30-2113001-00, 50-2113001-00	Cylinder	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-2500	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

107.	114256317	Bottom Valve Body	32-31	Messier-Dowty	Repair	LTI Repair Scheme #245-2501	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
108.	D62587, D62587-1, D67836, GA63977, GA63977-1, GA67308	Cylinder	32-33	Messier-Dowty	Repair	LTI Repair Scheme #245-2520	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
109.	D62329, GA63844-1	Body	32-33	Messier-Dowty	Repair	LTI Repair Scheme #245-2521	N/A	Minor Repair Approval by EASA DO21J
110.	758469-01	Support Assembly - Inversion Pump	24-11	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2711	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
111.	755812A, 757221-02, 757221-04, 757221-06	End Housing	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2715	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
112.	747298A thru E, 766229-01 thru -04	Input Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2750	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
113.	747101, 747101 A thru D	End Hsg & Support	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2801	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
114.	767870	Input Hsg	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2820	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
115.	769920	Input Hsg Assy	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2830	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
116.	4100766	Actuator Body	49-23	API Corp.	Repair	LTI Repair Scheme #250-0160	N/A	Minor Repair Approval by EASA DO21J
117.	624022	Adapter Block & Inserts Subassy	29-11	Eaton-Vickers	Repair	LTI Repair Scheme #250-0500	N/A	Minor Repair Approval by EASA DO21J
118.	623745	Valve Block & Inserts Subassy	29-11	Eaton-Vickers	Repair	LTI Repair Scheme #250-0501	N/A	Minor Repair Approval by EASA DO21J
119.	350874	Housing & Insert Subassy	29-11	Eaton-Vickers	Repair	LTI Repair Scheme #250-0512	N/A	Minor Repair Approval by EASA DO21J
120.	401465, 428122, 570035, 861716	Adapter Block & Inserts Subassy	29-11	Eaton-Vickers	Repair	LTI Repair Scheme #250-0520	N/A	Minor Repair Approval by EASA DO21J
121.	570031, 570033	Valve Block & Insert Subassy	29-11	Eaton-Vickers	Repair	LTI Repair Scheme #250-0523	N/A	Minor Repair Approval by EASA DO21J
122.	20670	Port Cap Subassy	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-0530	N/A	Minor Repair Approval by EASA DO21J
123.	4102111-1	Bearing Housing	29-11	Triumph	Repair	LTI Repair Scheme #250-0540	N/A	Minor Repair Approval by EASA DO21J
124.	4112316-1, 4112316-2	Variable Housing	29-11	Triumph	Repair	LTI Repair Scheme #250-0541	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

	125.	4112315-1	Housing - Manifold Valve Assy	29-11	Triumph	Repair	LTI Repair Scheme #250-0542	N/A	Minor Repair Approval by EASA DO21J
	126.	971699	Housing Subassembly	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0560	N/A	Minor Repair Approval by EASA DO21J
	127.	973561	Mounting Flange	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0565	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
	128.	973012	Housing Subassembly	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0570	N/A	Minor Repair Approval by EASA DO21J
	129.	20766	Pump Housing Subassy	29-20	Parker Hannifin	Repair	LTI Repair Scheme #250-0650	N/A	Minor Repair Approval by EASA DO21J
	130.	3022053-201, 3022053-213	Adapter Block Subassy	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0730	N/A	Minor Repair Approval by EASA DO21J
	131.	3022053-202	Housing & Insert Subassy	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0731	N/A	Minor Repair Approval by EASA DO21J
	132.	974802	Housing & Insert Subassy	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0750	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
	133.	3022053-204, 861252, 3022053-313, 861251	Mounting Flange, Pin & Inserts Subassy	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0753	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
	134.	3022115-200, 370337, 418811	Housing - Insert & Pins Subassy	29-22	Eaton-Vickers	Repair	LTI Repair Scheme #250-0800	N/A	Minor Repair Approval by EASA DO21J
	135.	759489, 759605, 767022	Strut - Housing Assy	29-21	Hamilton Sundstrand	Repair	LTI Repair Scheme #250-0900	N/A	Minor Repair Approval by EASA DO21J
A	136.	26349, 26350, 26485, 26486, 27387, 27388, 25183, 25184, 26003, 26002	Front Housing Subassembly	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-2010	N/A	Minor Repair Approval by EASA DO21J
	137.	24973	Mounting Flange Subassy	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-2011	N/A	Minor Repair Approval by EASA DO21J
A	138.	26471, 26472, 25175, 26719, 26720, 27389, 27390, 27443, 27444	Port Cap Subassy	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-2012	N/A	Minor Repair Approval by EASA DO21J
	139.	24808-02, 24809-02, 24809-03	Housing	29-20	Parker Hannifin	Repair	LTI Repair Scheme #250-2020	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
	140.	24806-02	Port Cap Subassy	29-20	Parker Hannifin	Repair	LTI Repair Scheme #250-2022	N/A	Minor Repair Approval by EASA DO21J
	141.	8927-9	Transfer Tube	32-50	Messier-Dowty	Repair	LTI Repair Scheme #250-4010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

142.	24773	Port Cap Subassy	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-4020	N/A	Minor Repair Approval by EASA DO21J
143.	821050-1	Valve Housing - P2.2 Shutoff Valve	36-13	Hamilton Sundstrand	Repair	LTI Repair Scheme #250-4030	N/A	Minor Repair Approval by EASA DO21J
144.	26477	Mounting Flange Subassy	29-10	Parker Hannifin	Repair	LTI Repair Scheme #250-7801	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
145.	26283	Mounting Flange Subassy	29-11	Parker Hannifin	Repair	LTI Repair Scheme #250-7801	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
146.	1708456-1 thru -3, 738462, 728775, 752111, 752135, 1701493-1 thru -3, 728776, 752119, 1701493-1WE, 1701493-2WE, 1701493-3WE, 753534, 753543, 755116, 755550-1 thru -3, 756415, 756416, 761845, 761852, 765474-1 thru -8, 766221-1 thru -4, 766225-1, 765475-1, 771698-1 thru -3, D765475-1, 765866-1, 765866-2, 765867-1, 765867-2, 766225-5, 767274-1, 765116, 747594, 747595, 749588, 771463, 771464, 771697-1 thru -3, 771698-1 thru -3, 771761, 771762, 767265-1, 728775JP, 761852JP	Sleeve	24-15	Hamilton Sundstrand	Repair	LTI Repair Scheme #250-9099	N/A	Minor Repair Approval by EASA DO21J
147.	746388, 757061	Control Housing Assy	24-14	Hamilton Sundstrand	Repair	LTI Repair Scheme #250-9100	N/A	Minor Repair Approval by EASA DO21J
148.	721287	Control Housing	24-14	Hamilton Sundstrand	Repair	LTI Repair Scheme #250-9120	N/A	Minor Repair Approval by EASA DO21J
149.	86113-101, 86113-201	Waste Drain Valve - Ball	38-30	LGG Luftfahrtgeräte	Repair	LTI Repair Scheme #253-0001	N/A	Minor Repair Approval by EASA DO21J
150.	882707-1, 882707-3	Barrel	29-12	Parker Hannifin	Repair	LTI Repair Scheme #255-0020	N/A	Minor Repair Approval by EASA DO21J
151.	882751-103	MANIFOLD ASSEMBLY	29-12	Parker Hannifin	Repair	LTI Repair Scheme #255-0040	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

152.	73011, 73009, 73010	Housing Assy	29-11	Pneudraulics Inc.	Repair	LTI Repair Scheme #255-0070	N/A	Minor Repair Approval by EASA DO21J
153.	3923094-3, 3923094-501	Cap - Subassy	32-10	Goodrich Aerospace	Repair	LTI Repair Scheme #255-0130	N/A	Minor Repair Approval by EASA DO21J
154.	49805-3, 49805-103	Housing - Subassy	32-10	Goodrich Aerospace	Repair	LTI Repair Scheme #255-0131	N/A	Minor Repair Approval by EASA DO21J
155.	41610-3	Cylinder Assy	32-31	Menasco Aerospace	Repair	LTI Repair Scheme #255-0500	N/A	Minor Repair Approval by EASA DO21J
156.	103583200, 103583300	Cylinder	32-31	Messier-Dowty	Repair	LTI Repair Scheme #255-0520	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
157.	974708-2	Inlet Body	21-50	Honeywell (Allied Sig)	Repair	LTI Repair Scheme #255-1010	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
158.	52351-3, 52351-103	Housing Assy	32-51	Goodrich Aerospace	Repair	LTI Repair Scheme #255-2701	N/A	Minor Repair Approval by EASA DO21J
159.	8906-3, 8908-3	Lined Gland	32-50	Messier-Dowty	Repair	LTI Repair Scheme #255-4011	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
160.	741496	Pump Sleeve	24-15	Hamilton Sundstrand	Repair	LTI Repair Scheme #255-9098	N/A	Minor Repair Approval by EASA DO21J
161.	5863080-103 thru -107, 5863080-109, 5863080-110	Actuator Body	75-24	Parker Hannifin	Repair	LTI Repair Scheme #280-0010	N/A	Minor Repair Approval by EASA DO21J
162.	4A7304, 4A7304A	Oil Pressure Pump Assy	79-21	Avio	Repair	LTI Repair Scheme #280-0030	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
163.	1667-9003, 1778-3000, 1798-3000	Inserts & Plug Body Assy	75-31	Goodrich Aerospace	Repair	LTI Repair Scheme #280-0100	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
164.	1656-1045, 1656-1057, 1666-9004, 1666-9005, 1727-3002, 1768-3000	Inserts & Plug Body Assy	75-38	Goodrich Aerospace	Repair	LTI Repair Scheme #280-0110	N/A	Minor Repair Approval by EASA DO21J
165.	1655-9004, 1685-3001	Body, Insert - Plug & Bearing	75-32	Goodrich Aerospace	Repair	LTI Repair Scheme #280-0200	N/A	Minor Repair Approval by EASA DO21J
166.	3169904-2, 3169904-3, 3169904-5	Valve Body	21-51	Allied Signal	Repair	LTI Repair Scheme #415-2260	N/A	Minor Repair Approval by EASA DO21J
167.	217621-1, 217621-2	Pump Cover Assembly	73-11	ArgoTech	Repair	LTI Repair Scheme #425-2181	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
168.	215371	Relief Valve Hsg	73-11	ArgoTech	Repair	LTI Repair Scheme #425-2541	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
169.	1211318-102, 1211318-103	Actuator Housing Assembly (Body)	75-32	Arkwin Industries	Repair	LTI Repair Scheme #205-0650-1	N/A	Minor Repair Approval by EASA DO21J
170.	3504749-1	Housing – Exhaust/Carrier	80-11	Honeywell	Repair	LTI Repair Scheme #205-3010	N/A	Minor Repair Approval by EASA DO21J

LUFTHANSA TECHNIK INTERCOAT GMBH COMPANY MAINTENANCE CAPABILITY LIST

CAAC Certificate No: F04900358

Date: October 23rd, 2025

Revision No.: 11

171.	752712, 752712A, 755275, 755275A, 755275B, 755275C, 755275D, 755275E	Input Housing Assembly	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2710	N/A	Minor Repair Approval by EASA DO21J
172.	772316, 1721001	End Housing Assembly	24-17	Hamilton Sundstrand	Repair	LTI Repair Scheme #245-2831	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
173.	971699	Housing Subassembly	29-10	Eaton-Vickers	Repair	LTI Repair Scheme #250-0560-1	N/A	Minor Repair Approval by EASA DO21J
174.	974805	Adapter Block – Variable Displacement Hydraulic Pump	29-10	Eaton – Vickers	Repair	LTI Repair Scheme #250-0741	N/A	Minor Repair Approval by EASA DO21J
175.	26375, 26369	Front Hsg Subassy	29-10	Parker Hannifin	Repair	LTI Repair Scheme #250-7802	Mitutoyo Coordinate Measuring Machine	Minor Repair Approval by EASA DO21J
176.	32P0045	Bearing Compartment Scavenge Valve Unit	79-23	Safran & IAE	Repair	LTI Repair Scheme #280-0400	N/A	Minor Repair Approval by EASA DO21J
	END							

A = Amendment / item added

R = Revised